

Jet MD-81 Mouse Function Correlation

Click on knob switches between SPD and MACH selection mode

For turning off THROTTLE warning on FMA click on switch

Click in HDG window, switches HDG 180°

Click on HDG knob; HDG HLD
Double click on HDG knob; HDG SEL

For turning off AP warning on FMA click on switch

Click and hold down mouse button for more than 1/2 sec. switches in 100ft selection mode. Double click arms ALT preselect mode.



Gear Up

Gear Down

Flaps Up

Flaps Down

Trim Nose Up

Trim Nose Down

Jet MD-81 Hardware Function Correlation

